

# Insulated Butt Connector

- Usage: connect wires, cables, electrical products
- Material: copper
- Tools required: tools clamp



## ITEMS:

Catalog No	Model	IMAX	Dimensions (mm)			Wire Range		isolated color	Quantity in bag	Quantity in carton (bag)
			L	DØ	I	mm <sup>2</sup>	A.W.G			
MWT50010331	BV1.25	19A	26	1.7	15	1.5~0.5	22~16	● red	100	120
MWT50010332	BV2	27A	26	2.3	15	2.5~1.5	16~14	● blue	100	96
MWT50010333	BV5.5	48A	26	3.4	15	6~4	12~10	● yellow	100	60
MWT50010334	BV8	62A	32	4.5	21	10~6	#8	● red	100	60
MWT50010335	BV14	88A	42	5.8	26	16~10	#6	● blue	100	60
MWT50010336	BV22	115A	50	7.7	29	25~16	#4	● yellow	100	60
MWT50010337	BV38	160A	55	9.4	32	50~35	#2	● red	100	36

Catalog No	Model	IMAX	Dimensions (mm)			Wire Range		isolated color	Quantity in bag	Quantity in carton (bag)
			L	DØ	I	mm <sup>2</sup>	A.W.G			
MWT50010338	PVT1.25	19A	16	1.7	8	1.5~0.5	22~16	● red	100	240
MWT50010339	PVT2	27A	16	2.3	8	2.5~1.5	16~14	● blue	100	120
MWT50010340	PVT5.5	48A	20.5	3.4	8.5	6~4	12~10	● yellow	100	60

## SKETCHES: mm

